And the second s

C-O-N-Y-I-D-	F-X-T-I-A-L	SEE BOTTON O	PAGE FOR SPECI	AL CONTROLS, IF ANY	]
INFOR	MATION RE	This material contains information affecting the National Detence of the United States within the			
PREPARED AND DISSEM	INATED BY		meaning of the Espionage Laws. Title 18, U.S.C. Secs. 793 and 794, the transmission or revelation		
CENTRAL	INTELLIGENCE	of which in say manner to an unautherised per- son is prohibited by law.		50X	
VSSR	ें   विद   हो	t i tanganta ayan sayan sa	PEPURT	-	1
31818 f	A CONTRACTOR OF THE PARTY OF TH	The state of the s	DATE DIS	ep-mathetic distribution of	
Road Buta -	Madvormaya, Kolo Vicinity	ayya, Stanislav &	NO OF PAGES	NO OF ENGLS	
1		5.1 19. – 1	SUPPLEMENT TO REP	TREE TREE TREE	50
P ACT 4/ Q THED (By source)	}- (	The state of the s	+ -	a company and a programme and	}
		stween which,	no c		
1				•	
	THIS IS	UNEVALUATED INFORM	IATION		1

A hard-surfaced, all-weather road (No 924 on legand) ran from Stanislav (Stanislawow) southward to Medvormaya (Medworma) via Bogorodchany and Detroye. This same type of a hard-surfaced, all-weather road (No 924 on legend) rem from Hadvornaya southward toward Delystin, them it turned eastward to Kolomyya (Kolomyja). Another hard-surfaced, all-weather read (No 92k on legend) ran from Stanislav eastward to Tysmenites (Tysmenicheny) then it vecred off and went south southwest to Hadvornaya.

The above roads were considered to be first class highways. The roads were designed and constructed for heavy usage. The roads had a very solid base or crushed rock. The top layer consisted of crushed rock surfaced with a and .

The roads were compacted by old-fashioned equipment. Brainage ditches ran along both sides of the roads. The roads were over eight maters wide and were crowned for easy drainage. The roads were maintained and repaired by assigned work crews. Piles of stone, gravel, and sand were located in certain sections along the roads to be used in repair work of the roads.

A loose-surfaced, graded, all-weather road (No 903 on legend) ran from Ugorniki south southwest to Tsutsilov. Ugorniki is a small village located approximately one to two kilometers east of Stanislav. This same type of a loose-surfaced, graded, all-weather road (No 903 on legend) ran from Tysmenitsa eastward them southeast to Gorodenka (Horodenka). Another loosesurfaced, graded, all-weather road (No 903 on legend) ran from Khryplin south so s sutheast toward Kolomyra, where it joined the highway which ran from Madvornaya to Kolomyya.


The roads were over eight meters vide and were crowned. Drainage ditches ran along both sides of the roads. A soft shoulder approximately one meter wide also ram alongside the roads. The subbase of the roads consieted of crushed rock and the top layer was of crushed rock and surfaced with sand, and compacted by old-fashioned rollers. They were also periodically inspected and maintained by assigned work crews.

A number of loose-surfaced, dry-weather dirt roads (No 935 on legend) ran buth southwest, south and southeast of Stanislav. These dirt roads were

C-O-H-P-I-D-H-H-T-I-A-L

## BEST COPY Available

eclassified in Part - Sanitized Copy Approved for Release @ 50-Yr2013/05/15 : CIA-RDP82-00047R00060019000			
· · · · · · · · · · · · · · · · · · ·	te de la companya de		
	. <b>2 -</b>	ILLEGIB	
<i>r</i>			
		•	
5			



50X1

